

# ASP TRI-FOLD RESTRAINTS

---

Recently there have been serious security events where some Flight Attendants have encountered a "failure" when applying the ASP Tri-Fold restraints to a passenger. Applying the restraints is a **"team effort"** and requires 2 or more crew members or the assistance of available "Able Body Passengers (ABP)". The restraints should be applied as tight as possible and necessary. As a "best practice" and to ensure the restraints remain in place on a passenger after proper application, it is recommended that Flight Attendants also apply the security restraint tape. If you do not have the company issued security tape, request a roll from your local base Flight Service MOD office. If the security tape is not available at your base, send an email to [safety@apfa.org](mailto:safety@apfa.org) for follow up with the base.

If you encounter a problem or failure applying the ASP Tri-Fold restraints during an in-flight security event, communicate and coordinate with the Flight Deck officers immediately. Include all details in the appropriate company report following the event.

A new training video for the ASP Tri-Fold restraints will be available for all Flight Attendants at CQ and via the Crew Security web site for those Flight Attendants who have already attended their annual CQ training.